Exam : HP0-265

Title : Servicing HP Color LaserJet

MFP Printers, High-End

Version: DEMO

1. What is the service strategy for the ADF on the Color LaserJet 8550mfp?

A.clean and adjust first, then replace whole unit if necessary

B.replace whole ADF and perform adjustments

C.replace all internal ADF parts and perform adjustments

D.clean and adjust first, then replace the entire copy module

Correct:A

2. Which components comprise the anti-counterfeiting process built into the Color LaserJet 8550mfp? Select TWO.

A.ECO1 pcb B.reader

controller C.currency

line reader D.ECO2

pcb Correct:A D

3. Which components come standard on an Color LaserJet 8550mfp? Select TWO.

A.printer engine

B.automatic document feeder

C.copy module

D.1000-sheet HCI

Correct: A C

4. How do you change the display language of the copy module of the Color LaserJet 8550mfp? Select TWO.

A.use Web JetAdmin

B.flash copy module firmware C.use

the printer control panel D.install a

firmware localization DIMM Correct:B

D

5. What is the order in which color planes are developed on the transfer drum of a Color LaserJet 8550mfp?

A.black, yellow, cyan, magenta

B.magenta, yellow, cyan, black

C.black, yellow, magenta, cyan

D.yellow, magenta, cyan, black

Correct:D

6.Which functions cannot be performed on the Color LaserJet 8550mfp? Select TWO.

A.scan and print color documents

B.scan and store a job

C.scan and print monochrome documents

D.scan and send documents to e-mail

Correct:B D

7. The customer complains of print quality problems in red and blue colors repeating at a frequency of 38mm on a Color LaserJet 8550mfp. What is the most likely cause of this defect?

A. The magenta toner cartridge is running low on toner or has a defect.

B.The cyan toner cartridge is running low on toner or has a defect.

C.The yellow toner cartridge is running low on toner or has a defect.

D.The black toner cartridge is running low on toner or has a defect.

Correct:A

8. When using the ADF on a Color LaserJet 8550mfp, the original-set indicator begins flashing. What is the likely cause?

A.jam in print engine

B.incorrect paper size in ADF

C.ADF paper jam

D.incorrect media type

Correct:C

9. The functionality of ZoomSmart on a Color LaserJet 8550mfp, allows a user to _____.

A.reduce the information on the page

B.use a fit to page option

C.scale the document based on paper size

D.scale the document by entering an exact scale %

Correct:C

10. Which input tray cannot be used on a Color LaserJet 8550mfp when making copies?

A.1000-sheet HCI

B.tray 1

C.tray 2

D.tray 3

Correct:A

Trying our product!

- ★ 100% Guaranteed Success
- ★ 100% Money Back Guarantee
- ★ 365 Days Free Update
- ★ Instant Download After Purchase
- ★ 24x7 Customer Support
- ★ Average 99.9% Success Rate
- ★ More than 69,000 Satisfied Customers Worldwide
- ★ Multi-Platform capabilities Windows, Mac, Android, iPhone, iPod, iPad, Kindle

Need Help

Please provide as much detail as possible so we can best assist you.

To update a previously submitted ticket:





Guarantee & Policy | Privacy & Policy | Terms & Conditions

Any charges made through this site will appear as Global Simulators Limited.

All trademarks are the property of their respective owners.

Copyright © 2004-2014, All Rights Reserved.