

100% Money Back Guarantee

Vendor: HP

Exam Code: HP3-042

Exam Name: HP LaserJet 5200 Series Printers Service and Support

Version: Demo

QUESTION NO: 1

How many motors do HP LaserJet 5200 series printers contain?

- A. 1
- B. 2
- C. 3
- D. 4

Answer: D

QUESTION NO: 2

What printer drivers are included on the inbox CD for the HP LaserJet 5200 series printer? Select THREE.

- A. Linux
- B. PCL 5e
- C. PostScript 3
- D. PCL 6

Answer: B,C,D

QUESTION NO: 3

When removing/replacing the assembly, for which internal assembly must you first remove the cartridge door unit?

- A. control panel assembly
- B. laser/scanner assembly
- C. face down delivery unit
- D. cassette-paper pickup unit

Answer: B

QUESTION NO: 4

Which of the following are customer self-repair parts? Select THREE.

-
- A. tray 1 pickup roller
 - B. formatter
 - C. memory DIMMs
 - D. main fan duct

Answer: A,B,C

QUESTION NO: 5

The HP LaserJet 5200L comes with which two of the following? Select TWO.

- A. 500-sheet input tray
- B. one open DIMM slot
- C. duplex unit
- D. hi-speed USB 2.0 port

Answer: B

QUESTION NO: 6

What type of page would you print for information about jams, loading trays, or supported media types and sizes?

- A. Show Me How
- B. Configuration
- C. Device Information
- D. Self-help

Answer: A

QUESTION NO: 7

Which unit, or units, must be removed when removing the high-voltage power supply?

- A. cartridge door unit
- B. registration unit
- C. both the cartridge door unit and the registration unit
- D. neither the cartridge door unit nor the registration unit

Answer: B

QUESTION NO: 8

What is the heaviest paper supported in trays 2 and 3 on the HP LaserJet 5200 series printer?

- A. 75 g/m² (20 lb)
- B. 90 g/m² (24 lb)
- C. 120 g/m² (32 lb)
- D. 199 g/m² (53 lb)

Answer: C

QUESTION NO: 9

What happens if the formatter and DC controller are replaced at the same time?

- A. The NVRAM remains blank and the printing device needs to be reset.
- B. The 'Save and Restore' feature does not properly store new memory on the NVRAM.
- C. The printing device perceives the DC controller as being reused, and rejects the new controller.
- D. The printing device does not recognize the newly applied serial number, and does not come to a 'Ready' state during power-up.

Answer: D

QUESTION NO: 10

After a formatter is replaced, how much time is needed after the device comes to 'Ready' for the NVRAM settings to be rewritten?

- A. 1 minute
- B. 3 minutes
- C. 5 minutes
- D. 7 minutes

Answer: C

To Read the [Whole Q&As](#), please purchase the [Complete Version](#) from [Our website](#).

Trying our product !

- ★ **100%** Guaranteed Success
- ★ **100%** Money Back Guarantee
- ★ **365 Days** Free Update
- ★ **Instant Download** After Purchase
- ★ **24x7** Customer Support
- ★ Average **99.9%** Success Rate
- ★ More than **69,000** Satisfied Customers Worldwide
- ★ Multi-Platform capabilities - **Windows, Mac, Android, iPhone, iPod, iPad, Kindle**

Need Help

Please provide as much detail as possible so we can best assist you.

To update a previously submitted ticket:



 One Year Free Update <p>Free update is available within One Year after your purchase. After One Year, you will get 50% discounts for updating. And we are proud to boast a 24/7 efficient Customer Support system via Email.</p>	 Money Back Guarantee <p>To ensure that you are spending on quality products, we provide 100% money back guarantee for 30 days from the date of purchase.</p>	 Security & Privacy <p>We respect customer privacy. We use McAfee's security service to provide you with utmost security for your personal information & peace of mind.</p>
---	---	--

[Guarantee & Policy](#) | [Privacy & Policy](#) | [Terms & Conditions](#)

Any charges made through this site will appear as Global Simulators Limited.

All trademarks are the property of their respective owners.

Copyright © 2004-2015, All Rights Reserved.